

Annual Returns form for Health Care Facilities / Common Bio-medical Waste Treatment and Disposal Facility (CBWTF)


PCB ID : 157666

Health Care Facility / CBWTF Name : Birla Fertility & Ivf (A Unit Of C K Birla Healthcare Pvt Ltd)

1	Year	2024
2	Type of Health Care Facility	Bedded Hospital Private
3	Number of Beds	3
4	License Number and Date of Expiry of License	AWB119755 11/02/20
5	Do you have Captive Treatment Facility ?	<input type="radio"/> Yes <input checked="" type="radio"/> No

Quantity of Waste Generated or Disposed in Kg per annum (on monthly average basis)

6	Yellow Category	15
7	Red Category	3.5
8	White Category	0
9	Blue Category	0
10	General Solid Waste	80



Details of the Storage, Treatment, Transportation, Processing and Disposal Facility

11	Details of the on-site storage facility	SEGREGATED TEMPRARY STORAGE BMW BINS
12	Treatment Facility	---
13	Quantity of Recyclable Waste sold to Authorized Recyclers after Treatment (in kg / Year)	0
14	Number of Vehicles used for Collection and Transportation of Biomedical Waste	1




Signature

15	Details of Incineration Ash and ETP Sludge generated and disposed during the Treatment of waste (in Kg / Year)	0
16	Name of the Common Bio-Medical Waste Treatment Facility Operator through which waste are disposed of	Hoswin Incinerator Pvt. Ltd
17	Do you have bio-medical waste management committee ? If yes, minutes of the meetings held during the reporting period	<input checked="" type="radio"/> Yes <input type="radio"/> No COMMITTEE MEETING IN EVERY 3 MONTHS

Details of Trainings conducted on Bio Medical Waste Management

18	Number of Trainings conducted on BMW Management	2
19	Number of Personnel Trained	15
20	Number of Personnel Trained at the time of Induction	
21	Number of Personnel not undergone any Training so far	0
22	Whether standard manual for Training is available ?	<input checked="" type="radio"/> Yes <input type="radio"/> No
23	Any other information	NA

Details of the accident occurred during the year

24	Number of Accident occurred	0
25	Number of the persons affected	0
26	Remedial Action taken (details if any)	NA
27	Any Fatality Occurred , details	NA
28	Are you meeting the standards of air Pollution from the incinerator ? How many times in last year could not met the standards?	<input checked="" type="radio"/> Yes <input type="radio"/> No
29	Details of Continuous Online Emission Monitoring systems	NA <div style="text-align: right;">  </div>

	installed	
30	Liquid waste generated and treatment methods in place . How many times you have not met the standards in a year	0
31	Is the disinfection method or sterilization meeting the log 4 standards ? How many times you have not met the standards in a year ?	<input type="radio"/> Yes <input checked="" type="radio"/> No
32	Any other relevant information	NA
Update		



HOSWIN Incinerator Pvt. Ltd.

An ISO 14001 : 2015, 45001 : 2018, 9001 : 2015 Certified Organization
Best Practice Award By UN Habitat & Business Excellence Award By Economic Development Forum

Report No. HOS/2024/ 224

Client ID CL4813

To Whom So Ever It May Concern

This is to certify that following quantity (In Kg.) of Bio Medical Waste received from

NAME: Birla Health Care (Fertility) Pvt Ltd

ADDRESS: 2nd FLOOR, THE BUSINESS BAY, OPP CHL HOSPITAL,

had been treated & disposed by us as per guidelines for the Period from Jan-24 To Dec-24

Year - 2024					
Month	YELLOW	RED	WHITE	BLUE	TOTAL KG.
Jan-24	1.20		-	-	1.20
Feb-24	1.40	-	-	-	1.40
Mar-24	0.50	-	-	-	0.50
Apr-24	3.00	-	-	-	3.00
May-24	0.50	-	-	-	0.50
Jun-24	1.90	-	-	-	1.90
Jul-24	1.80	-	-	-	1.80
Aug-24	-	0.20	-	-	0.20
Sep-24	0.70	0.60	-	-	1.30
Oct-24	0.40	1.20	-	-	1.60
Nov-24	3.80	-	-	-	3.80
Dec-24	-	1.30	-	-	1.30
Total	15	3	-	-	18.50

For : Hoswin Incinerator Pvt. Ltd.

Auth: Signature

Date: 20/01/2025



309-310 Vikram Urban, Naidunia Building, Near Girdhar Mahal, Vijay Nagar, Indore (M.P.).

◆ Mob. : 9755644433 Web. : www.hoswinindia.com ◆ Email : info.hoswin@gmail.com